




Drawer installation to the cabinet.




Front panel adjustment.



Drawer disassembly.



Drawer removal



OÜ OSMARGO

Suur-Paala 13

13619 Tallinn

Estonia

tel.: +372 638 10 18

osmargo@osmargo.ee

www.osmargo.ee

 **SMARGO**  
ÖÖBLIFURNITUUR